





Report Date: 8th July 2008
Report Compiled By: Neil Stapleton



Station Frontage & Approach

Signs & Poster Cases	OK
Pigeon Nets	All areas directly over pavement OK
 Station Frontage	Wall to the left of the entrance is reasonably clean. The brickwork of walls to the right of the entrance is very slimy and needs to be cleaned.



Entrance & Lower Stairway

 Litter Bin	Replacement fitted in mid-June.
Poster Cases	OK
Stairs	OK – swept by FOWS mid-June.
Walls (whitewashed)	Walls fairly clean.
 Walls (above whitewash)	Some vegetation growing and generally quite dirty.
 Roof	Very dirty. Two damaged planks in ceiling.
Lights	OK

Booking Hall

Poster Cases	OK
Walls (lower)	Reasonably clean.
 Walls (upper)	Dirty.
 Roof	In general need of maintenance.
Lights	OK

Upper Stairway

Poster Cases	OK.
Stairs	OK – swept by FOWS mid-June.
Walls (whitewashed)	OK.
 Walls (above whitewash)	Dirty.
 Roof	Leaks badly onto stairs and walls during rain due to recent theft of flashing from roof.
Lights	OK

Platform & Canopy

😊	Litter Bin	Replacement fitted in mid-June.
	Shelter & Seats	OK, seats currently being repainted.
😊	Canopy	Currently being repainted.
😞	Platform Surface	Possible signs of subsidence by 3 rd pillar on South (down) platform.
	Platform Edge	White line OK
	North (Up) Flower Bed	Good condition, no problems this month. Some summer bedding added by FOWS.
	South (Down) Flower Bed	Good condition, no problems this month. Some summer bedding added by FOWS.
	Free-standing Planters	Good condition, no problems this month.
	Platform Signs	OK

Photographs

None	
------	--