




Report Date: 6<sup>th</sup> August 2008  
Report Compiled By: Neil Stapleton



### Station Frontage & Approach

Signs & Poster Cases	OK
Pigeon Nets	All areas directly over pavement OK
 Station Frontage	Wall to the left of the entrance is reasonably clean. The brickwork of walls to the right of the entrance is very slimy and needs to be cleaned.



### Entrance & Lower Stairway

Litter Bin	Replacement hoop-and-bag bin fitted in mid-June is still in situ.
Poster Cases	OK
Stairs	OK.
Walls (whitewashed)	Walls fairly clean.
 Walls (above whitewash)	Some vegetation growing and generally quite dirty (see photo A).
 Roof	Dirty. Two damaged planks in ceiling near street wall are leaking into entrance way when raining (photo B). In need of general care and cleaning.
Lights	OK

### Booking Hall

Poster Cases	OK
Walls (lower)	Reasonably clean.
 Walls (upper)	Dirty.
 Roof	In general need of maintenance. Booking Office staff report severe leaking from roof in office during rain.
Lights	OK

### Upper Stairway


Poster Cases	OK.
Stairs	OK but need thorough sweeping to remove dust and wood shavings from canopy renovation.
Walls (whitewashed)	Some staining from leaking roof (photo C).
 Walls (above whitewash)	Dirty.
 Roof	Leaks badly onto stairs and walls during rain due to theft of flashing from roof in May (photo D).

Lights	OK
--------	----

### Platform & Canopy

Litter Bin	Replacement hoop-and-bag bin fitted in mid-June is still in situ.
Shelter & Seats	OK, seats repainted navy blue.
😊 Canopy	Repainting in tasteful navy blue, silver and white colour scheme was completed on 4 <sup>th</sup> August and now looks very smart (photo E).
Platform Surface	Possible signs of long-term subsidence by 3 <sup>rd</sup> pillar on South (down) platform. Weeds covering open area of platform have been removed this month by FOWS
Platform Edge	White line OK
North (Up) Flower Bed	Good condition but several new plants have had to be planted by FOWS to replace stolen and vandalised Busy Lizzies.
South (Down) Flower Bed	Good condition having been weeded and replenished by FOWS this month. A new holly bush has been planted in the problem area near the stairway entrance where persistent urinating has killed all previous plants.
Free-standing Planters	Good condition, no problems this month.
Platform Signs	OK

### Photographs

<p><b>Photo A</b></p> <p>The wall above the entrance way showing ferns growing from the brickwork and extensive mould/lichen growth.</p>	
--	--

**Photo B**

The roof of the entrance way showing broken roof timbers.



**Photo C**

Staining on the upper stairway walls caused by leaks from the stairway roof.



**Photo D**

The upper flight of stairs showing extensive puddles and wet surfaces after rain.



**Photo E**

The canopy repainting has finished this month and has greatly improved the platform area's appearance.

This was the most heavily overflowing pillar before being cleaned out during the repainting work.

