








Report Date: 5th November 2008
Report Compiled By: Neil Stapleton




Station Frontage & Approach

	Signs & Poster Cases	Graffiti on "Walkden" station sign directly over street entrance.
	Pigeon Nets	All areas directly over pavement OK
	Station Frontage	Wall to the left of the entrance is reasonably clean. The brickwork of walls to the right of the entrance is very slimy and needs to be cleaned.



Entrance & Lower Stairway

	Litter Bin	Missing since 21 st Sept.
	Poster Cases	Smashed poster cases have been replaced by GMPTE.
	Stairs	OK.
	Walls (whitewashed)	Main items of graffiti around site of missing litter bin have been painted out, some small items remaining.
	Walls (above whitewash)	Generally dirty.
	Roof	Dirty. Two damaged planks in ceiling near street wall are leaking into entrance way when raining. In need of general repair and cleaning.
	Lights	OK

Booking Hall

	Poster Cases	Damaged poster case opposite ticket office window has been replaced by ISS.
	Walls (lower)	Reasonably clean.
	Walls (upper)	Dirty.
	Roof	In need of general repairs. Booking Office staff report severe leaking from roof in office during rain. No plans for Network Rail to repair until FY 2009.
	Lights	OK

Upper Stairway

	Poster Cases	OK.
	Stairs	Because of the leaking roof the stairs get wet during rain and passengers have been seen slipping on the greasy surface.
	Walls (whitewashed)	Badly stained by water from leaking roof.
	Walls (above whitewash)	Dirty.

☹️ Roof	Leaks badly onto stairs and walls during rain due to theft of flashing from roof in May.
Lights	OK

Platform & Canopy

☹️ Litter Bin	Missing since 21 st Sept.
Shelter & Seats	OK. Some graffiti on shelter.
Canopy	OK
☹️ Pillars	Grffiti reported last month has been painted over. 3 rd pillar on up platform showing fresh signs of rusting since recent repainting – this pillar’s gutter is clearly not working properly (see photo C)
Platform Surface	Possible signs of long-term subsidence by 3 rd pillar on South (down) platform.
Platform Edge	White line OK
North (Up) Flower Bed	OK. New winter flowers planted by FOWS this period.
South (Down) Flower Bed	OK.
Free-standing Planters	OK.
☹️ Platform Signs	“No Smoking” sign stolen from top of stairs (see Photo A).
☹️ North (Up) platform walls.	Grffiti reported last month has been painted over. Yellow safety sign has been pulled further away from wall since last month (see photo B).
South (Down) platform walls.	OK.

Photographs


<p>Photo A</p> <p>Missing “No Smoking” sign at top of stairs.</p>	
--	--

Photo B

Vandalised safety notice on Manchester (up) platform.



Photo C

Rust damage on up platform 4th pillar.

