

Report Date: 6th April 2008
Report Compiled By: Neil Stapleton

Station Frontage & Approach

Signs & Poster Cases	OK
Pigeon Nets	All areas directly over pavement OK
☹ Station Frontage	Walls to the left of the entrance have recently been cleaned by FOWS and are reasonably clean. The brickwork of walls to the right of the entrance is very slimy and needs to be cleaned.

Entrance & Lower Stairway

☹ Litter Bin	Missing
Poster Cases	OK
Stairs	OK
Walls (whitewashed)	Some new graffiti. Walls are fairly clean having recently been scrubbed by FOWS.
☹ Walls (above whitewash)	Some vegetation growing and generally quite dirty (see photo A).
☹ Roof	Very dirty. Two damaged planks in ceiling.
Lights	OK

Booking Hall

Poster Cases	OK
Walls (lower)	Reasonably clean (recently cleaned by FOWS)
☹ Walls (upper)	Very dirty. Some stickers above ticket window out of reach from ground level.
☹ Roof	Football lodged in rafters.
Lights	OK

Upper Stairway




☹ Poster Cases	Some graffiti on Police poster case.
Stairs	OK
Walls (whitewashed)	Clean having been scrubbed by FOWS this morning (extensive mud & blood stains removed).
☹ Walls (above whitewash)	Very dirty.
☹ Roof	Leak from a broken conduit visible in corner above Police poster case (photo B).
Lights	OK

Platform & Canopy

☹ Litter Bin	Missing
Shelter & Seats	OK

☹️	Canopy	Leaking badly near 1 st pillar (from entrance) on South platform. Water dripping on platform and running down pillar causing rusting (photo C). Considerable rusting also seen on 1 st & 3 rd pillars on N platform.
☹️	Platform Surface	Possible signs of subsidence by 3 rd pillar on S platform.
	Platform Edge	White line OK
	North Flower Bed	Plants destroyed by vandals have mostly been replaced.
	South Flower Bed	Vandalised plants are mostly replaced and new bedding plants have been added.
☹️	Platform Signs	2 of the 8 signs have minor graffiti.
☹️	Other	Broken guttering pipe attached to wall beyond ramp at W end of S platform (photo D).

Photographs

A. Dirty walls with vegetation above lower stairway.	
B. Broken conduit leaking into upper stairway.	
C. Leaking canopy and rusting pillar on S platform.	
D. Broken guttering	