



Report Date: 14th April 2009
Report Compiled By: Neil Stapleton



Station Frontage & Approach

Signs & Poster Cases	OK.
Pigeon Nets	All areas directly over pavement OK
Station Frontage	Stone and brickwork around the doorway OK. The untreated brick of the walls to the right of the entrance is very slimy and needs to be cleaned.




Entrance & Lower Stairway

	Litter Bin	Vandalised bin has been replaced.
	Poster Cases	OK.
	Stairs	OK.
	Walls (whitewashed)	OK.
	Walls (above whitewash)	Generally dirty. A cable is hanging loosely from the wall near the entrance.
	Roof	Dirty. Two damaged planks in ceiling near street wall are leaking into entrance way when raining. In need of general repair and cleaning.
	Lights	OK

Booking Hall





	Poster Cases	OK.
	Walls (lower)	OK.
	Walls (upper)	Dirty.
	Roof	In need of general repairs. Booking Office staff report severe leaking from roof in office during rain.
	Lights	OK

Upper Stairway

	Poster Cases	OK
	Stairs	Because of the leaking roof the stairs get wet during rain and passengers have been seen slipping on the greasy surface.
	Walls (whitewashed)	Badly stained by water from leaking roof.
	Walls (above whitewash)	Dirty.
	Roof	Leaks badly onto stairs and walls during rain due to theft of flashing from roof in May 2008.

Lights	OK.
--------	-----

Platform & Canopy

	Litter Bin	Still missing.
	Shelter & Seats	OK.
	Canopy	OK. The pigeon loft in the ceiling has been boarded up as requested.
	Pillars	1 st and 3 rd pillar on up platform show fresh signs of rusting since 2008 repainting.
	Platform Surface	Platform surface has been cleaned by ISS. Although some fresh pigeon droppings have re-appeared the situation is much improved on last month. Possible signs of long-term subsidence by 3 rd pillar on South (down) platform.
	Platform Edge	White line OK, becoming quite faded now. "Mind The Gap" warnings have not yet been added.
	North (Up) Flower Beds	OK. Fresh planting installed by FOWS and wooden border repainted.
	South (Down) Flower Bed	OK. Fresh planting installed by FOWS. Holly at far end of bed has been cut back by ISS, presumably to prevent roof safety sign being obscured.
	Free-standing Planters	OK. Fresh planting installed by FOWS.
	Platform Signs	OK.
	North (Up) platform walls.	OK.
	South (Down) platform walls.	OK.