



Report Date: 14th June 2009
Report Compiled By: Neil Stapleton



Station Frontage & Approach

Signs & Poster Cases	OK.
Pigeon Nets	All areas directly over pavement OK
Station Frontage	Stone and brickwork around the doorway OK. The untreated brick of the walls to the right of the entrance is very slimy and needs to be cleaned.


Entrance & Lower Stairway

Litter Bin	OK.
Poster Cases	OK.
Stairs	Generally OK. Like the upper stairway, is in need of a deep clean and repainting of faded stair-edge lines.
Walls (whitewashed)	OK.
 Walls (above whitewash)	Loose electric cable has been re-fastened to the wall. General condition of walls remains dirty.
 Roof	Dirty. Two damaged planks in ceiling near street wall are leaking into entrance way when raining. In need of general repair and cleaning.
Lights	OK

Booking Hall

Poster Cases	OK.
Walls (lower)	OK.
 Walls (upper)	Dirty.
 Roof	Still appears to be leaking from cracked conduit in ceiling at end of Booking Hall.
Lights	All working OK. Evidence of pigeons trying to establish nests on top of the first light cage.

Upper Stairway

Poster Cases	OK
 Stairs	Swept by FOWS. Lines on step-edges are fading and need to be repainted. The stairs are generally dirty, have numerous patches of dried chewing gum, and need a thorough clean. Because of the leaking roof the stairs get wet during rain and passengers have slipped on the greasy surface.

	Walls (whitewashed)	Badly stained by water from leaking roof.
☹	Walls (above whitewash)	Dirty.
☹	Roof	Leaks badly onto stairs and walls during rain due to theft of flashing from roof in May 2008.
	Lights	OK.

Platform & Canopy

☹	Litter Bin	Still missing.
	Shelter & Seats	OK. Shelter roof is extremely dirty.
	Canopy	OK.
☹	Pillars	1 st and 3 rd pillar on up platform show fresh signs of rusting since 2008 repainting. 1st pillar is presumed to be blocked as this pillar is quickly becoming more heavily stained with rust.
	Platform Surface	Excessive amounts of pigeon mess on platform surface. Possible signs of long-term subsidence by 3 rd pillar on South (down) platform.
	Platform Edge	"Mind The Gap" warnings have not yet been added.
	North (Up) Flower Beds	OK. Weeded by FOWS.
	South (Down) Flower Bed	A severe outbreak of green & white fly has decimated the first 2 meters of this bed. Several bags of dead plants have been removed and the area treated by FOWS.
	Free-standing Planters	OK.
	Platform Signs	OK.
	North (Up) platform walls.	OK.
	South (Down) platform walls.	OK.