



Report Date: 23<sup>rd</sup> March 2009  
Report Compiled By: Neil Stapleton



### Station Frontage & Approach

Signs & Poster Cases	Signage is very clean having been jet washed by JetClean this month. Poster cases OK.
Pigeon Nets	All areas directly over pavement OK
Station Frontage	Stone and brickwork around the doorway have been cleaned by JetClean this month. The untreated brick of the walls to the right of the entrance is very slimy and needs to be cleaned.


### Entrance & Lower Stairway




 Litter Bin	Replaced this month but already missing again.
Poster Cases	OK.
Stairs	OK.
Walls (whitewashed)	OK.
Walls (above whitewash)	Generally dirty.
 Roof	Dirty. Two damaged planks in ceiling near street wall are leaking into entrance way when raining. In need of general repair and cleaning.
Lights	OK

### Booking Hall





Poster Cases	OK.
Walls (lower)	OK.
 Walls (upper)	Dirty.
 Roof	In need of general repairs. Booking Office staff report severe leaking from roof in office during rain.
Lights	OK

### Upper Stairway

Poster Cases	OK
 Stairs	Because of the leaking roof the stairs get wet during rain and passengers have been seen slipping on the greasy surface.
Walls (whitewashed)	Badly stained by water from leaking roof.

	Walls (above whitewash)	Dirty.
	Roof	Leaks badly onto stairs and walls during rain due to theft of flashing from roof in May 2008.
	Lights	The top pair of lights have been fixed.

### Platform & Canopy

	Litter Bin	Replaced this month but already missing again.
	Shelter & Seats	Missing panel from shelter has been replaced and graffiti removed.
	Canopy	OK
	Pillars	1 <sup>st</sup> and 3 <sup>rd</sup> pillar on up platform show fresh signs of rusting since 2008 repainting.
	Platform Surface	Staff have cleaned pigeon mess from the platform surface last month but it is already badly affected by more droppings deposited since. Several parts of the platform are "no-go" areas for passengers and the mess presents a health & safety hazard. Pigeons are nesting in the canopy which is the likely cause of the increased incidence of this problem.  Possible signs of long-term subsidence by 3 <sup>rd</sup> pillar on South (down) platform.
	Platform Edge	White line OK, becoming quite faded now. "Mind The Gap" warnings have not yet been added.
	North (Up) Flower Beds	Minor theft of plants. Fresh planting installed by FOWS.
	South (Down) Flower Bed	Some evidence of aborted plant theft (a plant dug up and placed in a plastic bag but not removed). Fresh planting installed by FOWS.
	Free-standing Planters	OK – no damage this period.
	Platform Signs	OK.
	North (Up) platform walls.	OK.
	South (Down) platform walls.	OK.