

Report Date: 14th September 2008
Report Compiled By: Neil Stapleton

Station Frontage & Approach

Signs & Poster Cases	OK
Pigeon Nets	All areas directly over pavement OK
☹ Station Frontage	Wall to the left of the entrance is reasonably clean. The brickwork of walls to the right of the entrance is very slimy and needs to be cleaned.

Entrance & Lower Stairway

Litter Bin	OK
Poster Cases	OK
Stairs	OK.
Walls (whitewashed)	Walls fairly clean.
☹ Walls (above whitewash)	Generally dirty.
☹ Roof	Dirty. Two damaged planks in ceiling near street wall are leaking into entrance way when raining. In need of general repair and cleaning.
Lights	OK

Booking Hall

Poster Cases	OK
Walls (lower)	Reasonably clean. Some graffiti problems this month – cleaned by station staff.
☹ Walls (upper)	Dirty.
☹ Roof	In general need of maintenance. Booking Office staff report severe leaking from roof in office during rain.
Lights	OK

Upper Stairway

Poster Cases	OK.
☹ Stairs	Swept by FOWS after canopy repainting was completed. Because of the leaking roof the stairs get wet during rain and FOWS have witnessed passengers slipping on the greasy surface.
Walls (whitewashed)	Staining from leaking roof.
☹ Walls (above whitewash)	Dirty.

☹️ Roof	Leaks badly onto stairs and walls during rain due to theft of flashing from roof in May.
Lights	OK

Platform & Canopy

Litter Bin	Replacement hoop-and-bag bin fitted in mid-June is still in situ.
☹️ Shelter & Seats	Graffiti on shelters windows and frame.
☹️ Canopy	20 or more separate pieces of graffiti on canopy girders (see photos E-F). Reported to BTP by FOWS this morning.
☹️ Pillars	Graffiti on 3 rd & 4 th down platform pillars and 4 th up platform pillar (see photos A-C). 3 rd pillar on up platform showing fresh signs of rusting since recent repainting – this pillar's gutter is clearly not working properly.
Platform Surface	Possible signs of long-term subsidence by 3 rd pillar on South (down) platform.
Platform Edge	White line OK
North (Up) Flower Bed	OK. Weeded by FOWS 14/09/08.
South (Down) Flower Bed	OK. Weeded by FOWS 14/09/08.
Free-standing Planters	Graffitied this week but cleaned by FOWS.
Platform Signs	2 signs turned round wrong way – reset by FOWS.

Photographs


<p>Photo A</p> <p>Graffiti on down platform 3rd pillar.</p>	
---	--

Photo B

Graffiti on down platform 4th pillar.



Photo C

Graffiti on up platform 4th pillar.



Photo D

Rust damage on up platform 4th pillar.



Photo E

Graffiti in the canopy rafters.



Photo F

Graffiti in the canopy rafters.

