

Report Date: 5<sup>th</sup> October 2008  
Report Compiled By: Neil Stapleton

## Station Frontage & Approach

☹	Signs & Poster Cases	Graffiti on "Walkden" station sign directly over street entrance.
	Pigeon Nets	All areas directly over pavement OK
☹	Station Frontage	Wall to the left of the entrance is reasonably clean. The brickwork of walls to the right of the entrance is very slimy and needs to be cleaned.

## Entrance & Lower Stairway

☹	Litter Bin	Missing since 21 <sup>st</sup> Sept.
☹	Poster Cases	Two poster cases nearest street have smashed perspex covers since 21 <sup>st</sup> Sept. (see photo C).
	Stairs	OK.
☹	Walls (whitewashed)	Graffiti around site of missing litter bin.
☹	Walls (above whitewash)	Generally dirty.
☹	Roof	Dirty. Two damaged planks in ceiling near street wall are leaking into entrance way when raining. In need of general repair and cleaning.
	Lights	OK

## Booking Hall

☹	Poster Cases	Poster case opposite ticket office window has knife damage to perspex cover since 21 <sup>st</sup> Sept.
	Walls (lower)	Reasonably clean.
☹	Walls (upper)	Dirty.
☹	Roof	In general need of maintenance. Booking Office staff report severe leaking from roof in office during rain.
	Lights	OK

## Upper Stairway


	Poster Cases	OK.
☹	Stairs	Swept by FOWS after canopy repainting was completed. Because of the leaking roof the stairs get wet during rain and FOWS have witnessed passengers slipping on the greasy surface.
	Walls (whitewashed)	Staining from leaking roof.
☹	Walls (above whitewash)	Dirty.

☹️ Roof	Leaks badly onto stairs and walls during rain due to theft of flashing from roof in May.
Lights	OK

### Platform & Canopy

☹️ Litter Bin	Missing since 21 <sup>st</sup> Sept.
Shelter & Seats	OK.
😊 Canopy	OK – canopy repainted by Northern since graffiti in rafters reported last month.
☹️ Pillars	Graffiti reported last month has been painted over. 3 <sup>rd</sup> pillar on up platform showing fresh signs of rusting since recent repainting – this pillar's gutter is clearly not working properly (see photo D)
Platform Surface	Possible signs of long-term subsidence by 3 <sup>rd</sup> pillar on South (down) platform.
Platform Edge	White line OK
North (Up) Flower Bed	OK. Weeded by FOWS today. Needs more winter flowers – FOWS to plant next week.
South (Down) Flower Bed	OK. Weeded by FOWS today.
Free-standing Planters	OK.
Platform Signs	OK.
☹️ North (Up) platform walls.	Fresh graffiti this weekend (see photos A & B). Yellow safety sign has been pulled partly away from wall.
South (Down) platform walls.	OK.

### Photographs

<p><b>Photo A</b></p> <p>Graffiti on north platform wall.</p>	
---	--

**Photo B**

Missing litter bin and graffiti on north platform wall.



**Photo C**

Poster cases with smashed perspex covers.



**Photo D**

Rust damage on up platform 4<sup>th</sup> pillar.

