

Report Date: 6th May 2008
Report Compiled By: Neil Stapleton

Station Frontage & Approach

Signs & Poster Cases	OK
Pigeon Nets	All areas directly over pavement OK
☹ Station Frontage	Walls to the left of the entrance have recently been cleaned by FOWS and are reasonably clean. The brickwork of walls to the right of the entrance is very slimy and needs to be cleaned.

Entrance & Lower Stairway

☹ Litter Bin	Replaced in mid-April but now missing again.
Poster Cases	OK
Stairs	OK – swept on 4 th May by FOWS.
Walls (whitewashed)	Walls fairly clean.
☹ Walls (above whitewash)	Some vegetation growing and generally quite dirty.
☹ Roof	Very dirty. Two damaged planks in ceiling.
Lights	OK

Booking Hall

Poster Cases	OK
Walls (lower)	Reasonably clean.
☹ Walls (upper)	Very dirty.
☹ Roof	Football lodged in rafters.
Lights	OK

Upper Stairway

☹ Poster Cases	Some graffiti on Police poster case.
Stairs	OK – swept on 4 th May by FOWS.
Walls (whitewashed)	Clean having been cleaned last month by FOWS.
☹ Walls (above whitewash)	Very dirty.
Roof	Broken conduit in corner above Police poster case appears to have been fixed.
Lights	OK


Platform & Canopy

☹ Litter Bin	Replaced in mid-April but now missing again.
Shelter & Seats	OK

☹️	Canopy	Leaking badly near 1 st pillar (from entrance) on South platform. Water dripping on platform and running down pillar causing rusting (photo A). Considerable rusting also seen on 1 st & 3 rd pillars on N platform.
☹️	Platform Surface	Possible signs of subsidence by 3 rd pillar on S platform.
	Platform Edge	White line OK
	North Flower Bed	Good condition.
	South Flower Bed	Replenished with additional bedding plants on 4 th May, half a dozen of which were pulled out & thrown on track by the next morning.
	Free-standing Planters	Installed by FOWS on 4 th May (photo B).
☹️	Platform Signs	2 of the 8 signs have minor graffiti.

Photographs

A. Water leaking badly on 1st pillar on South platform.



B. Free-standing planters installed by FOWS this month.

